<u>HIREDEPOT</u> <u>Submersible Pumps – HAZARD ASSESSMENT</u>

The Identified Hazard	Risk Yes/ No	The Proposed Method of Control Measure	Are The Control Methods Practical
Persons could be injured if the operator performs duties that are not his responsibility and beyond the scope of his technical capabilities.	Yes	The operator should be adequately trained or licensed. The operator must not carry out any work that is outside his normal duties and report any matters of concern to his supervisor.	Yes
Persons could be injured as a result of electrocution.	Yes	Do not lower pump by the lead, use the rope provided. Use a power supply protected by a safety switch. Do not use with faulty leads or plugs. Ensure equipment is tested/tagged for compliance with electrical safety testing requirements. Disconnect power before moving or checking pump. Do not enter water when power to pump is connect.	Yes
Persons could be injured from water exiting the pump.	Yes	Ensure the hose is correctly attached before starting.	Yes
Persons could be injured if they slip, trip or fall whilst using the pump.	Yes	Take care when walking around wet and slippery surfaces.	Yes
Persons could be injured if the machine operator is unfamiliar with typical unsafe conditions and hazards that could affect the safe operation of the unit.	Yes	The operator should be trained in determining unsafe conditions and hazards that are relative to the machine's safe operation.	Yes
Persons could be injured if personal protective equipment is not available or being used when working in an unsatisfactory environment e.g. noise, heat, fumes, etc.	Yes	Instruct the operator to ensure that appropriate personal protective equipment is available and is in good condition prior to commencing work. Only operate in a well ventilated area.	Yes
Persons could be injured as a result of fire or explosion.	Yes	Do not use pump for flammable or hazardous materials. Do not use pump near a potentially explosive environment.	Yes

Mandatory Personal Protective Equipment:





Customer Signature:	